

**United States Department of the Interior
National Park Service
Historic Preservation Certification Application**

Instructions

Completing Part 2 – Examples.

If using a computer-generated version of the certification application, fonts may be changed to a larger size and boxes may be enlarged if additional space is needed.

Number 1	<p>Architectural feature: <u>facade brick</u></p> <p>Approximate date of feature: <u>ca. 1880</u></p> <p>Describe existing feature and its condition:</p> <p>Hard pressed red brick with butter joints in good condition. Mortar mostly sound, but deteriorated and missing around downspout at east end of facade. Some graffiti at first floor.</p> <p>Photo no. <u>3, 6</u> Drawing no. _____</p>	<p>Describe work and impact on existing feature:</p> <p>Will selectively hand clean deteriorated joints and repoint with mortar and joint width to match existing (see spec. pp. 33-35); chemically clean graffiti from first floor piers (see spec. pp. 30-31).</p>
Number 2	<p>Architectural feature <u>main staircase</u></p> <p>Approximate date of feature <u>ca. 1880</u></p> <p>Describe existing feature and its condition:</p> <p>Original stair exists between 1st and 3rd floors. Some balusters missing and treads worn. Later stair from 3rd to 8th floors..</p> <p>Photo no. <u>9, 10</u> Drawing no. <u>A-12</u></p>	<p>Describe work and impact on existing feature:</p> <p>Replace missing balusters with matching pieces. Sand painted banisters and balusters and varnish. Replace treads as needed. Sand and paint stairs. Retain later stair as is.</p>